


Disposal Instructions for Empty Tanks

1. Spray until the tank is completely empty and the spray gun does not emit any more glue and propellant.
2. Close the valve on the tank.
3. Then continue with the hose and spray until no more glue or propellant is emitted.
4. Turn the small cog behind the handle to close the gun and detach the hose from the empty tank. If possible, attach it to a new tank immediately, to avoid glue remnants from hardening within the hose. Open the valve as soon as the hose is attached to the new tank.
5. Now open the valve of the empty tank in a well-vented room, to make sure that the propellant has escaped completely from the tank.
6. Perforate the empty tank at the predetermined breaking point next to the valve.



7. Remove the hazardous goods label.
8. The tank now counts as scrap iron and can be disposed of.